

ABOUT REVISION P OF THE AT-MIO-16E-10

NI-DAQ Users

AT-MIO-16E-10 revision P boards require NI-DAQ version 5.1 or greater for Windows 95/NT, or version 5.0.4 for Windows 3.1x. If you have an earlier version of NI-DAQ, you must upgrade your driver software. AT-MIO-16E-10 revision P replaces revision C, which will be discontinued after November 1, 1998.

Register-Level Programmers

If you are doing register-level programming, use the *AT-MIO-E Series Register-Level Programmer Manual*, part number 340747C-01 or later (kit number 777189-01) for detailed register information. To determine which revision of the manual you have, refer to the part number on the cover or title page of the manual. The letter before the -01 is the revision letter.